

Fitting and Feedthrough Assembly Instructions

CAUTION: Conax Technologies Seal Fittings should be installed by suitably qualified personnel in accordance with relevant safety rules and with proper regard to safe working practices.

Conax Technologies Seal Fittings have lubricant applied at the factory. Substitution of factory-supplied lubricant will affect seal integrity. Lubrication prevents thread galling and minimizes friction between mating metallic components to maximize seal fitting performance when a catalog-specified torque is applied. Weld mount models should be relubricated after the body is welded in place. If the fitting has been cleaned before assembly, it should also be relubricated prior to assembly.

Lubricant should be used any time a seal fitting assembly is opened for replacement or adjustment of the probe(s), wires or sealant. By re-lubricating the fitting body threads and load bearing surface of the cap, proper load transfer (sealant compression) can be achieved. See page 124 for lubrication instructions.

Conax Technologies recommends the use of thread sealant tape or dopant on NPT threads during installation of the fitting to the vessel.


Flange mounted fittings should be assembled prior to mounting to the vessel.

CAUTION: Torque ratings are developed using solid stainless steel elements at 68 °F (20 °C). When sealing on soft, fragile or crushable elements, catalog torques may not apply. When catalog torques are applied, compressed sealants generate considerable forces on the element to be sealed. These forces could result in damaging soft or fragile elements such as coax cables or thin-wall materials. Consult factory for these types of applications.

A note on B Caps:

When using a seal fitting assembly with a B Cap, it is sometimes easy to confuse which NPT thread screws into the process side. If installed backwards, leakage will occur between the cap and body straight thread.

A hex notch (as shown below) has been added to the cap to simplify identification. When properly installed, the hex notch will appear on the non-process side of the assembly.




Please note: Fittings previously purchased may have "Conax" engraved on a cap hex surface in lieu of the hex notch. When properly installed, the lettering or hex notch will appear on the non-process side of the assembly (the cap). Please consult the factory with any questions before installing.

Throughout this catalog, feedthroughs (fittings with conductors) that are not supplied with Conax-installed conductors have an "XX" or "XX/XX" designation. Fittings without Conax-installed conductors are not pre-torqued, and it is the end user's responsibility to properly torque the feedthrough following installation of the conductor(s).

A note on Followers with Pins:

Many Conax fittings with multiple holes have followers with anti-rotation pins. In our Legacy products, the follower has a key way into which a separate pin (key) is inserted. Conax's current product line has followers with integral pins. As you read the numbered assembly instructions throughout this document, numbered steps with a letter "a" suffix (14a for example) will explain the process for assembling a fitting with separate pin (key). If a step has a "b" suffix (14b for example), this step describes the assembly process when using a follower with integral pin.



Guidelines for Sealant Replacement

Conax Technologies recommends the following procedures to facilitate sealant replacement:


1. Ensure that all system pressurization has been removed before beginning sealant replacement.
2. Untorque and remove the seal fitting cap.
3. Remove the follower and sealant. Depending on the application, the element may also need to be removed.

Follower Removal: Tight manufacturing tolerances are used between the follower OD and the bore of the seal fitting body. As the follower is extracted, a vacuum can be created between the follower and sealant, making it difficult to remove the follower by hand. It may be necessary to clamp the exposed portion of the follower with pliers or a similar tool to gain the additional clamping force needed to remove the follower. If this is necessary, take care to avoid damage to the follower.

Sealant Removal: Teflon™, Neoprene, and Viton™ sealants can generally be removed in one piece. GraFoil™ and Lava sealants must be removed in multiple pieces, using a rigid "picking" instrument to break apart the sealant. During this process, be careful to avoid damage to the seal fitting body. Deep scratches or gouges may result in potential leak paths during future use of the fitting assembly.

4. Thoroughly clean the internal configuration of the seal fitting body with de-ionized water or cleaning alcohol (depending on the application) to remove any sealant residue.
5. Reassemble per applicable assembly instructions.

For Hex-Style PG/HPG Series Fittings



For assembly separate from the vessel:

1. Verify that the total probe length is sufficient for your desired immersion.
2. Thread the cap over the probe with the female thread facing the process (see diagram).
3. Thread the follower over the probe. For MPG and PG2 assemblies with bores smaller than 0.093", the follower may have a larger bore on one side. The larger bore diameter must be adjacent to the cap and the smaller bore diameter adjacent to the sealant.
4. Be sure you are using the correct sealant for your working pressure and temperature. Thread the sealant over the probe with the cone facing the process.
5. Thread the fitting body over the probe.
6. Slide the sealant into the fitting body.
7. Slide the follower after the sealant.
8. Push on the follower until the sealant is firmly seated.
9. Thread the cap on finger tight.
10. Secure the fitting body into a vice.
11. Make the final adjustment of immersion length.
12. Using a torque wrench, tighten the cap to the specified torque (see chart).
13. The assembly is now ready for use. Apply a wrench to the fitting body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:

1. Verify that the total probe length is sufficient for your desired immersion.
2. Mount the fitting body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.
3. Thread the cap over the probe with the female thread facing the process (see diagram).
4. Thread the follower over the probe so that the follower is between the cap and the process. For MPG and PG2 assemblies with bores smaller than 0.093", the follower may have a larger bore on one side. The larger bore diameter must be adjacent to the cap and the smaller bore diameter adjacent to the sealant.
5. Be sure you are using the correct sealant for your working pressure and temperature. Thread the sealant over the probe so that the sealant is between the follower and the process, and the cone of the sealant faces the process.
6. Insert the probe through the body into the process.
7. Slide the sealant into the fitting body.
8. Slide the follower after the sealant.

9. Push on the follower until the sealant is firmly seated.
10. Thread the cap on finger tight.
11. Make the final adjustment of immersion length.
12. Apply a backer wrench to the fitting body flats to prevent rotation during torquing.
13. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
14. The assembly is now ready for use.

PG Series Torque Requirements


Part Number	Neoprene/Viton™		Teflon™		Lava		GraFoil™	
	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m
MIC	N/O	N/O	7-9 in-lbs	0.8-1	45-50 in-lbs	5-5.6	45-50 in-lbs	5-5.6
MPG	55-60 in-lbs	6.2-6.7	55-60 in-lbs	6.2-6.7	75-80 in-lbs	8-9	55-60 in-lbs	6.2-6.7
PG2	30-35	40-48	15-20	20-27	40-45	54-61	35-40	48-54
PG4	55-60	74-82	55-60	74-82	125-140	170-190	90-100	122-136
PG5	55-60	74-82	90-100	122-136	200-220	272-299	180	244
PG6	165-170	224-231	300-325	408-442	N/O	N/O	N/O	N/O

N/O = Not Offered.

HPG Series Torque Requirements

Part Number	PEEK™	
	ft-lbs	N-m
HPG2	30	40
HPG4	75	102
HPG5	180	244

For Large Bore, Flange/Cap PG Series Fittings



For assembly separate from the vessel:


1. Verify that the total length of the cable/probe provides sufficient length for your desired immersion and leads.
2. Thread the flange/cap over the probe (see diagram).
3. Thread the follower over the probe.
4. Be sure you are using the correct sealant for your working pressure and temperature. Thread the sealant over the probe with the cone facing the process. (Sealant may be in more than one layer.)
5. Thread the fitting body over the probe.
6. Slide the sealant into the fitting body.
7. Slide the follower after the sealant.
8. Push on the follower until the sealant is firmly seated.

- Slide the flange/cap into place after the follower.
- Insert the 6 cap screws in place and finger tighten.
- Secure the fitting body into a vice.
- Make the final adjustment of immersion length.
- Using a torque wrench, tighten the cap screws to the specified torque (see chart). The cap screws should be progressively tightened in the order 1-4-2-5-3-6.
- The assembly is now ready for use. Apply a wrench to the fitting body flats for mounting to the vessel.

Large Bore PG Series Torque Requirements							
Part Number	Viton™		Lava		GraFoil™		Teflon™
	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	
Standard 1-1/4 NPT							
PG7-50	35	48	35	48	35	48	C/F
PG7-1000	14	19	35	48	35	48	C/F
PG7-75P	35	48	35	48	35	48	C/F
PG7-1250	14	19	35	48	35	48	C/F
PG7-100P	35	48	35	48	35	48	C/F
Weld Neck Mount (Weld Neck Length 1.01")							
PG7(SWM7/S316L)-50P	35	48	35	48	35	48	C/F
PG7(SWM7/S316L)-1000	14	19	35	48	35	48	C/F
PG7(SWM7/S316L)-75P	35	48	35	48	35	48	C/F
PG7(SWM7/S316L)-1250	14	19	35	48	35	48	C/F
PG7(SWM7/S316L)-100P	35	48	35	48	35	48	C/F

C/F = Consult Factory. For PG8 and PG9 torques, please consult factory.

For Hex-Style EG Series



EG Series Seal Fittings are shipped from the factory already torqued to the correct value and ready for installation. These instructions are provided in the event you choose to disassemble and need to reassemble the fitting or if you provide your own electrode. Weld mount styles are shipped untorqued, as the fitting must be disassembled prior to welding to protect the sealant.

For assembly separate from the vessel:

- Be sure you are using the correct sealant for your working pressure and temperature.
- Thread one ceramic insulator over the electrode (see diagram).
- Thread the sealant over the electrode. The tapered end of the sealant should face the process. Note: EG-375 and EG-500 Lava sealants use a two-piece cone and cup design. Insert the cup first with the tapered end facing away from the process. Then insert the cone so that the tapered end fits inside the cup. The cone must face the process.
- Thread the second ceramic insulator over the electrode.
- Insert the insulators, sealant and electrode as assembled into the fitting body until the ceramic insulator is stopped by the shoulder in the fitting. Hold the electrode to prevent it from dropping through.
- Thread the follower over the insulator. Seat the undercut edge onto the insulator shoulder.
- Thread the cap onto the body until finger tight.
- Secure the fitting body into a vice.
- Adjust the electrode to the correct position ensuring that the ceramic insulators are firmly seated and aligned.
- Using a torque wrench, tighten the cap to the specified torque (see chart).
- Install the nuts and washers on the non-process side of the assembly.
- Mount the assembly to the vessel. Apply a wrench to the fitting body flats—not the cap—when mounting to the vessel.
- Install the nuts and washers on the process side of the assembly.
- Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
- The assembly is now ready for use.


For assembly directly into a vessel:

- Be sure you are using the correct sealant for your working pressure and temperature.
- Mount the fitting body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.
- Thread one ceramic insulator over the electrode (see diagram).
- Thread the sealant over the electrode. The tapered end of the sealant should face the process. Note: EG-375 and EG-500 Lava sealants use two-piece cone and cup designs. Insert the cup first with the tapered end facing away from the process. Then insert the cone so that the tapered end fits inside the cup. The cone must face the process.
- Thread the second ceramic insulator over the electrode.
- Insert the insulators, sealant and electrode as assembled into the cap thread end of the fitting body until the ceramic insulator is stopped by the shoulder in the fitting. Hold the electrode to prevent it from dropping through.

- Thread the follower over the insulator. Seat the undercut edge onto the insulator shoulder.
- Thread the cap onto the body until finger tight.
- Adjust the electrode to the correct position ensuring that the ceramic insulators are firmly seated and aligned.
- Apply a backer wrench to the fitting body flats to prevent rotation during torquing.
- While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
- Install the nuts and washers on the non-process side of the assembly.
- Install the nuts and washers on the process side of the assembly.
- Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
- The assembly is now ready for use.

EG Series Torque Requirements				
Part Number	Neoprene/Teflon™/Viton™		Lava	
	ft-lbs	N-m	ft-lbs	N-m
EG-093	17-20	23-27	10-12	13-16
EG-125	25-30	34-40	25-30	34-40
EG-187	25-30	34-40	25-30	34-40
EG-250	40-45	54-61	60-65	81-88
EG-312	35-40	48-54	50-55	68-74
EG-375	50-55	68-74	180-200	244-272
EG-500	50-55	68-74	180-200	244-272

For EG-750 (Flange/Cap)



EG Series Seal Fittings are shipped from the factory already torqued to the correct value and ready for installation. These instructions are provided in the event you choose to disassemble and need to reassemble the fitting or if you provide your own electrode. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.

For assembly separate from the vessel:

- Be sure you are using the correct sealant for your working pressure and temperature.
- Thread one ceramic insulator over the electrode (see diagram). Note: The longer insulator must be used on the body side (toward the process).
- Thread the sealant over the electrode. The tapered end of

the sealant should face the process. Note: Lava sealants use two-piece cone and cup designs. Insert the cup first with the tapered end facing the process. Then insert the cone so that the tapered end fits inside the cup. The cone must face the process.


- Thread the short ceramic insulator over the electrode.
- Insert the insulators, sealant and electrode as assembled into the fitting body until the ceramic insulator is stopped by the shoulder in the fitting. Hold the electrode to prevent it from dropping through.
- Slide the flange/cap into place after the insulator.
- Insert the 6 cap screws in place and finger tighten.
- Secure the fitting body into a vice.
- Adjust the electrode to the correct position ensuring that the ceramic insulators are firmly seated and aligned.
- Use a torque wrench to tighten the cap screws to 10-12 ft-lbs (13-16 N-m) per bolt for Teflon™ or 25-30 ft-lbs (34-40 N-m) per bolt for Lava. The cap screws should be progressively tightened in the order 1-4-2-5-3-6.
- Install the nuts and washers on the non-process side of the assembly.
- Mount the assembly to the vessel. Apply a wrench to the fitting body flats when mounting to the vessel.
- Install the nuts and washers on the process side of the assembly.
- Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
- The assembly is now ready for use.

For assembly directly into a vessel:

- Be sure you are using the correct sealant for your working pressure and temperature.
- Mount the fitting body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.
- Thread one ceramic insulator over the electrode (see diagram). Note: The longer insulator must be used on the body side (toward the process).
- Thread the sealant over the electrode. The tapered end of the sealant should face the process. Note: Lava sealants use two-piece cone and cup designs. Insert the cup first with the flat side facing the process. Then insert the cone so that the tapered end fits inside the cup. The cone must face the process.
- Thread the short ceramic insulator over the electrode.
- Insert the insulators, sealant and electrode as assembled into the cap thread end of the fitting body until the ceramic insulator is stopped by the shoulder in the fitting. Hold the electrode to prevent it from dropping through.
- Slide the flange/cap into place after the insulator.
- Insert the 6 cap screws in place and finger tighten.
- Adjust the electrode to the correct position ensuring that the ceramic insulators are firmly seated and aligned.

10. Use a torque wrench to tighten the cap screws to 10-12 ft-lbs (13-16 N-m) per bolt for Teflon™ or 25-30 ft-lbs (34-40 N-m) per bolt for Lava. The cap screws should be progressively tightened in the order 1-4-2-5-3-6.
11. Install the nuts and washers on the non-process side of the assembly.
12. Install the nuts and washers on the process side of the assembly.
13. Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
14. The assembly is now ready for use.

For Hex-Style EGT/HEGPK Series



EGT and HEGPK Series Seal Fittings are shipped from the factory already torqued to the correct value and ready for installation. These instructions are provided in the event you choose to disassemble and need to reassemble the fitting or if you provide your own electrode. When using a weld mount, the fitting must be disassembled prior to welding to protect the Teflon™ sealant.

For assembly separate from the vessel:

1. Thread the Teflon™/PEEK™ sealant/insulator over the electrode. The tapered end must face the process (see diagram).
2. Insert the sealant/insulator and electrode as assembled into the fitting body until the sealant/insulator is stopped by the shoulder in the fitting. Hold the electrode to prevent it from dropping through the body.
3. Insert the follower.
4. Thread the cap onto the body until finger tight.
5. Secure the fitting body into a vice.
6. Adjust the electrode to the correct position ensuring that the sealant/insulator is firmly seated.
7. Using a torque wrench, tighten the cap to the specified torque (see chart).
8. Install the nuts and washers on the non-process side of the assembly.
9. Mount the assembly to the vessel. Apply a wrench to the fitting body flats—not the cap—when mounting to the vessel.
10. Install the nuts and washers on the process side of the assembly.

11. Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
12. The assembly is now ready for use.

For assembly directly into a vessel:


1. Mount the fitting body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.
2. Thread the Teflon™ sealant/insulator over the electrode. The tapered end must face the process (see diagram).
3. Insert the sealant/insulator and electrode as assembled into the cap thread end of the fitting body until the sealant/insulator is stopped by the shoulder in the fitting. Hold the electrode to prevent it from dropping through the body.
4. Insert the follower.
5. Thread the cap onto the body until finger tight.
6. Adjust the electrode to the correct position ensuring that the sealant/insulator is firmly seated and aligned.
7. Apply a backer wrench to the fitting body flats to prevent rotation during torquing.
8. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
9. Install the nuts and washers on the non-process side of the assembly.
10. Install the nuts and washers on the process side of the assembly.
11. Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
12. The assembly is now ready for use.

EGT/HEGPK Series Torque Requirements

Part Number	EGT Teflon™		HEGPK PEEK™	
	ft-lbs	N-m	ft-lbs	N-m
EGT-093	5-6	6-8	N/O	N/O
EGT/HEGPK-125	10-15	13-20	30	41
EGT/HEGPK-187	25-30	34-40	75	102
EGT/HEGPK-250	25-30	34-40	75	102
EGT/HEGPK-375	35-40	48-54	180	244
EGT/HEGPK-500	35-40	48-54	180	244
EGT-750	75-80	102-108	N/O	N/O

N/O = Not Offered.

For EGT-1000 (Flange/Cap)



EGT Series Seal Fittings are shipped from the factory already torqued to the correct value and ready for installation. These instructions are provided in the event you choose to disassemble and need to reassemble the fitting or if you provide your own electrode. When using a weld mount, the fitting must be disassembled prior to welding to protect the Teflon™ sealant.

For assembly separate from the vessel:

1. Thread the Teflon™ sealant/insulator over the electrode. The tapered end must face the process (see diagram).
2. Insert the sealant/insulator and electrode as assembled into the fitting body until the sealant/insulator is stopped by the shoulder in the fitting. Hold the electrode to prevent it from dropping through the body.
3. Insert the follower.
4. Slide the flange/cap into place after the follower.
5. Thread the 6 cap screws in place and finger tighten.
6. Secure the fitting body into a vice.
7. Adjust the electrode to the correct position ensuring that the sealant/insulator is firmly seated.
8. Use a torque wrench to tighten the cap screws to 54-60 in-lbs (6-7 N-m) per bolt. The cap screws should be progressively tightened in the order 1-4-2-5-3-6.
9. Install the nuts and washers on the non-process side of the assembly.
10. Mount the assembly to the vessel. Apply a wrench to the fitting body flats when mounting to the vessel.
11. Install the nuts and washers on the process side of the assembly.
12. Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
13. The assembly is now ready for use.


For assembly directly into a vessel:

1. Mount the fitting body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.
2. Thread the Teflon™ sealant/insulator over the electrode. The tapered end must face the process (see diagram).
3. Insert the sealant/insulator and electrode as assembled into the fitting body until the sealant/insulator is stopped

by the shoulder in the fitting. Hold the electrode to prevent it from dropping through the body.

4. Insert the follower.
5. Slide the flange/cap into place after the follower.
6. Insert the 6 cap screws in place and finger tighten.
7. Adjust the electrode to the correct position ensuring that the sealant/insulator is firmly seated and aligned.
8. Use a torque wrench to tighten the cap screws to 54-60 in-lbs (6-7 N-m) per bolt. The cap screws should be progressively tightened in the order 1-4-2-5-3-6.
9. Install the nuts and washers on the non-process side of the assembly.
10. Install the nuts and washers on the process side of the assembly.
11. Make the appropriate electrical connections to the electrode using ring-tongue, lug-type or spade terminals. These are positioned between the washers. The nuts should be tightened securely.
12. The assembly is now ready for use.

For MK Series



For assembly separate from the vessel:

1. Verify that the total length of the wire/probe provides sufficient length for your desired immersion and leads.
2. Thread the cap over the probe with the male thread facing the process (see diagram).
3. Thread the ferrule over the probe with the cone facing the process.
4. Thread the fitting body over the probe.
5. Slide the ferrule into the fitting body.
6. Thread the cap on finger tight.
7. Secure the fitting body into a vice.
8. Make the final adjustment of immersion length.
9. Using a torque wrench, tighten the cap to the specified torque (see chart).
10. The assembly is now ready for use. Apply a wrench to the fitting body flats for mounting to the vessel.

For assembly directly into a vessel:


1. Verify that the total length of the wire/probe provides sufficient length for your desired immersion and leads.
2. Mount the fitting body into the vessel wall.
3. Thread the cap over the probe with the male thread facing the process (see diagram).
4. Thread the ferrule over the probe with the cone facing the process.

5. Insert the probe through the body into the process.
6. Insert the ferrule into the fitting body.
7. Thread the cap on finger tight.
8. Make the final adjustment of immersion length.
9. Apply a backer wrench to the fitting body flats to prevent rotation during torquing.
10. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
11. The assembly is now ready for use.

MK Series Torque Requirements		
Part Number	Torque	
	ft-lbs	N-m
MK-062-A	10	13
MK-125-A	12	16
MK-187-A	18	24
MK-250-A	30	40
MK-375-A	50	68

For TG Series

For Models TG-14-1; TG-20, 2 & 4 hole; TG-24, 2 & 4 hole, all MTGs



For assembly separate from the vessel:

1. Verify that the total length of wire provides a sufficient length for your desired immersion and leads.
2. Thread the cap over the wires.
3. Thread the follower over the wires so that the keyway faces the cap.
4. Thread on insulator #4 (see diagram).
5. Thread on insulator #3.
6. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant so that the cone of the sealant faces the process.
7. Thread on insulator #2.
8. Thread insulator #1 over the wire.
9. Pass the process side of the wires through the body.
10. Slide the insulators and sealant into the body.
11. Slide the follower on over insulator #4 and insulator #3 until it completely covers insulator #3.
12. Push on the follower until the sealant and insulators are firmly seated. Be careful not to crimp the wires between the insulators and sealant.

- 13a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 13b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.


14. Thread the cap on finger tight.
15. Secure the feedthrough body into a vice.
16. Adjust the wires to the correct position.
17. Using a torque wrench, tighten the cap to the specified torque (see chart).
18. The assembly is now ready for use. Apply a wrench to the feedthrough body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:

1. Verify that the total length of wire provides a sufficient length for your desired immersion and leads.
2. Mount the feedthrough body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the feedthrough must be disassembled prior to welding to protect the sealant.
3. Thread the cap over the wires.
4. Thread the follower over the wires so that the keyway faces the cap.
5. Thread on insulator #4 (see diagram).
6. Thread on insulator #3.
7. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant so that the cone of the sealant faces the process.
8. Thread on insulator #2.
9. Thread insulator #1 over the wire.
10. Pass the process side of the wires through the body.
11. Slide the insulators and sealant into the body.
12. Slide the follower on over insulator #4 and insulator #3 until it completely covers insulator #3.
13. Push on the follower until the sealant and insulators are firmly seated. Be careful not to crimp the wires between the insulators and sealant.
- 14a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 14b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
15. Thread the cap on finger tight.
16. Adjust the wires to the correct position.
17. Apply a backer wrench to the feedthrough body wrench flats to prevent rotation during torquing.
18. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
19. The assembly is now ready for use.

For TG Series

For Models TG-8-2; TG-14, 2-8 hole; TG-18, 6 & 8 hole; TG-20, 6-16 hole



For assembly separate from the vessel:

1. Verify that the total length of wire provides a sufficient length for your desired immersion and leads.
2. Thread insulator #4 (see diagram) over the wire.
3. Thread the cap over the wire.
4. Thread the follower over the wires so that the keyway faces the cap.
5. Thread on insulator #3.
6. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant with the cone facing the process.
7. Thread on insulator #2.
8. Insert the wires and insulator assembly through the process end of the feedthrough body.
9. Thread insulator #1 over the wire until the insulator is stopped by the body shoulder.
10. Slide insulator #2 into the body until the insulator is stopped by the body shoulder.
11. Slide the sealant, followed by the follower, into the body.
12. Push on the follower until the sealant and insulators are firmly seated. Be careful not to crimp the wires between the insulators and sealant.
13. Slide insulator #4 so that it butts against the follower.

14a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.

14b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.

15. Thread the cap on finger tight.
16. Secure the feedthrough body into a vice.
17. Adjust the wires to the correct position.
18. Using a torque wrench, tighten the cap to the specified torque (see chart).
19. The assembly is now ready for use. Apply a wrench to the feedthrough body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:

1. Verify that the total length of wire provides a sufficient length for your desired immersion and leads.
2. Mount the feedthrough body into the vessel wall. This may be done by threading or welding,

depending on the mounting style. When using a weld mount, the feedthrough must be disassembled prior to welding to protect the sealant.

3. Thread insulator #4 (see diagram) over the wire.
4. Thread the cap over the wire.
5. Thread the follower over the wires so that the keyway faces the cap.
6. Thread on insulator #3.
7. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant with the cone facing the process.
8. Thread on insulator #2.
9. Insert the wires and insulator assembly through the process end of the feedthrough body.
10. Thread insulator #1 over the wire from the inside of the vessel and through the process side of the feedthrough body until the insulator is stopped by the body shoulder.
11. Slide insulator #2 into the body until the insulator is stopped by the body shoulder.
12. Slide the sealant, followed by the follower, into the body.
13. Push on the follower until the sealant and insulators are firmly seated. Be careful not to crimp the wires between the insulators and sealant.
14. Slide insulator #4 so that it butts against the follower.
- 15a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 15b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
16. Thread the cap on finger tight.
17. Adjust the wires to the correct position.
18. Apply a backer wrench to the feedthrough body wrench flats to prevent rotation during torquing.
19. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
20. The assembly is now ready for use.


TG Series Torque Requirements

Part Number	Holes	Neoprene		Viton™		Teflon™		Lava	
		ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m
MTG-24	2,4	20-25	27-34	20-25	27-34	20-25	27-34	30-35	40-48
MTG-20	2,4	20-25	27-34	20-25	27-34	20-25	27-34	30-35	40-48
MTG-14	1	20-25	27-34	20-25	27-34	20-25	27-34	30-35	40-48
TG-24	2,4	25-30	34-40	25-30	34-40	30-35	40-48	40-45	54-61
TG-20	2,4	25-30	34-40	25-30	34-40	30-35	40-48	40-45	54-61
TG-20	6,8	45-50	61-68	45-50	61-68	50-55	68-74	125-140	170-190
TG-20	16	75-85	102-115	75-85	102-115	75-85	102-115	200-220	272-299
TG-18	6,8	45-50	61-68	45-50	61-68	50-55	68-74	125-140	170-190
TG-14	1	25-30	34-40	25-30	34-40	30-35	40-48	40-45	54-61
TG-14	2,3,4	45-50	61-68	45-50	61-68	50-55	68-74	125-140	170-190
TG-14	6,8	75-85	102-115	75-85	102-115	75-85	102-115	200-220	272-299
TG-8	2	75-85	102-115	75-85	102-115	75-85	102-115	200-220	272-299
TG-20	24	N/A	N/A	95-100	129-136	95-100	129-136	300-310	408-422

N/A = Not Applicable.

Model TGF – TG Assembly with High Temperature Wire

Model TG-24T – TG Assembly with 24AWG Teflon™ Insulated Wire



Model TGF and TG-24T Series Seal Feedthroughs are shipped from the factory already torqued to the correct value and ready for installation. These instructions are provided for installation of the assembled feedthrough. In the event you choose to disassemble and need to reassemble the feedthrough, see the instructions for the MHC Series.

When using a weld mount, the feedthrough must be disassembled prior to welding to protect the sealant.

Recommended Method Using a Nipple-Union

Required Materials: Pipe Nipple, Schedule 40, Carbon Steel or Stainless Steel Union, 150 lb., Carbon Steel or Stainless Steel.

For longer length lead wires, this mounting method eliminates additional stress and potential wire entanglement caused by the rotation of the wires during the mounting operation.

1. Install the nipple and half union assembly into the vessel wall.
2. Uncoil and straighten the leads on the pressure side of the feedthrough.
3. Thread the mating half of the union over the leads.
4. Assemble the union onto the mounting thread of the seal feedthrough. Use the feedthrough body flats to hold/secure the feedthrough while mating the feedthrough with the union.
5. Pass the leads through the nipple-union assembly mounted on the vessel wall.
6. Position the two parts of the union and assemble the nipple-union assembly.
7. Remove wire markers on the process side after installation, as the adhesive-backed material could contaminate the process (depending on the application).

TGF Series Torque Requirements			
Catalog Number	Holes	Viton™/Teflon™	
		ft-lbs	N-m
MTG-F	2,4	72-78 in-lbs	8-9
TG-24F	2,4	10-12	13-16
TG-20F	2,4	10-12	13-16
TG-20F-14	2,4	25-30	34-40
TG-20F	6,8	25-30	34-40
TG-20F	16	60-65	81-88
TG-20F	24	70-75	95-102


TG-24T Series Torque Requirements

Catalog Number	Holes	Torque for Teflon™ Sealant w/ T/C Wire Except Type T		Torque for GraFoil™ Sealant and Teflon™ w/ Copper or Type T Wire	
		ft-lbs	N-m	ft-lbs	N-m
MTG-24T	2,4	20-25	24-34	72-78 in-lbs	8-9
TG-24T	2,4	30-35	40-48	10-12	13-16
TG-24T	6,8	50-55	68-74	25-30	34-40
TG-24T	12,16	75-85	102-115	60-65	81-88
TG-24T	24	95-100	129-136	70-75	95-102

Optional Method for TG-24T


1. Uncoil and straighten the leads on the pressure side.
2. Pass the leads through the mounting thread port on the vessel.
3. Screw/tighten the feedthrough into the vessel. Apply the wrench to the feedthrough body flats, not the cap.
4. Remove wire markers on the process side after installation, as the adhesive-backed material could contaminate the process (depending on the application).

For High Density Assemblies – HD Series



1. HD Feedthroughs may be supplied preinstalled on fitting either factory-torqued or loose (HD held in place with temporary tape). If factory-torqued, the HD/feedthrough assembly is ready for installation into your process. If the fitting is not factory-torqued onto the HD(s), then you should turn to the installation instructions for the appropriate fitting to review the proper torque rate to apply following installation of the feedthrough to the process and the HD to the fitting by using the following steps.
2. Secure the feedthrough body into the vessel wall. The remaining feedthrough parts are best assembled on a flat surface, such as a work table or a clean floor.
3. Install the seat and insulators if applicable, depending on the feedthrough type (see instructions for that feedthrough type).
4. Install the sealant.
5. Install the follower and pin if applicable.
6. Insert the leads through the feedthrough body and insert the high density assembly (as now assembled) into the body until the seat or insulator is firmly seated. Position the stainless steel sheath so that an approximately equal amount extends on each side of the feedthrough.
7. Thread the cap on finger tight.
8. Apply a backer wrench to the feedthrough body flats. Using a torque wrench, apply the appropriate torque for that feedthrough style.
9. The assembly is now ready for use.

MHC Series



For assembly separate from the vessel:

1. Verify that the total length of wire/probes provides a sufficient length for your desired immersion and leads.
2. Thread the cap over the wires.
3. Thread the follower over the wires so that the keyway faces the cap.
4. Thread on insulator #2 (see diagram).
5. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant with the cone facing the process.
6. Thread on insulator #1.
7. Pass the process side of the wires/probes through the body.
8. Slide the insulators, sealant and follower into the body.
9. Push on the follower until the sealant and insulators are firmly seated. For wire assemblies, be careful not to crimp the wires between the insulators and sealant.
- 10a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 10b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
11. Thread the cap on finger tight.
12. Secure the feedthrough body into a vice.
13. Adjust the wires to the correct position.
14. Using a torque wrench, tighten the cap to the specified torque (see chart).
15. The assembly is now ready for use. Apply a wrench to the feedthrough body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:

1. Verify that the total length of wire/probes provides a sufficient length for your desired immersion and leads.
2. Mount the feedthrough body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the feedthrough must be disassembled prior to welding to protect the sealant.
3. Thread the cap over the wires.
4. Thread the follower over the wires so that the keyway faces the cap.
5. Thread on insulator #2 (see diagram).
6. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant with the cone facing the process.


7. Thread on insulator #1.
8. Pass the process side of the wires/probes through the body.
9. Slide the insulators, sealant and follower into the body.
10. Push on the follower until the sealant and insulators are firmly seated. For wire assemblies, be careful not to crimp the wires between the insulators and sealant.
- 11a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 11b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
12. Thread the cap on finger tight.
13. Adjust the wires to the correct position.
14. Apply a backer wrench to the fitting body wrench flats to prevent rotation during torquing.
15. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
16. The assembly is now ready for use.

MHC Series Torque Requirements

Catalog Number	Neoprene		Viton™		Teflon™		Lava		GraFoil™	
	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m
MHC1	20-25	27-34	20-25	27-34	20-25	27-34	30-35	40-48	25-30	34-40
MHC2-020	25-30	34-40	25-30	34-40	30-35	40-48	40-45	54-61	35-40	48-54
MCH2-032	25-30	34-40	25-30	34-40	30-35	40-48	40-45	54-61	35-40	48-54
MHC2-040	25-30	34-40	25-30	34-40	30-35	40-48	40-45	54-61	40-45	54-61
MHC2-062	25-30	34-40	25-30	34-40	30-35	40-48	40-45	54-61	40-45	54-61
MCH4	45-50	61-68	45-50	61-68	50-55	68-74	125-140	170-190	90-100	122-136
MHC5	75-85	102-115	75-85	102-115	75-85	102-115	200-220	272-299	150-165	204-224
MHC5-032-24	N/O	N/O	95-100	129-136	95-100	129-136	300-310	408-422	250-265	340-360

N/O = Not Offered.

PL Series



PL Feedthroughs are shipped from the factory already torqued to the correct value and ready for installation. These instructions are provided in the event you choose to disassemble and reassemble the feedthrough. Weld mount styles are shipped untorqued as the feedthrough must be disassembled prior to welding to protect the sealant. PL Feedthroughs are provided with Teflon™ sleeves on the body and cap to protect against wire chafing. Do not remove these sleeves. When using a GraFoil™ sealant, the insulators on PL Feedthroughs are chamfered around the holes. Insulators for other sealants are not chamfered. Do not interchange.

For assembly separate from the vessel:

1. Verify that the total length of wire provides a sufficient length for your desired immersion and leads.
2. Thread on insulator #1 (see diagram).

3. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant with the cone facing the process.
4. Thread on insulator #2.
5. Slide on the follower, so that the keyway faces the cap.
6. Pass the process side of the wires through the body.
7. Push on the follower until the sealant and insulators are firmly seated. Be careful not to crimp the wires between the insulators and sealant.
- 8a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 8b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
9. Thread the cap on finger tight.
10. Secure the feedthrough body into a vice.
11. Adjust the wires to the correct position.
12. Using a torque wrench, tighten the cap to the specified torque (see chart).
13. The assembly is now ready for use. Apply a wrench to the feedthrough body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:

1. Verify that the total length of wire/probes provides a sufficient length for your desired immersion and leads.
2. Mount the feedthrough body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the feedthrough must be disassembled prior to welding to protect the sealant.
3. Thread on insulator #1 (see diagram).
4. Be sure you are using the correct sealant for your working pressure and temperature. Thread on the sealant with the cone facing the process.
5. Thread on insulator #2.
6. Slide on the follower, so that the keyway faces the cap.
7. Pass the process side of the wires through the body.
8. Push on the follower until the sealant and insulators are firmly seated. Be careful not to crimp the wires between the insulators and sealant.
- 9a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 9b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
10. Thread the cap on finger tight.
11. Adjust the wires to the correct position.
12. Apply a backer wrench to the feedthrough body flats to prevent rotation during torquing.
13. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
14. The assembly is now ready for use.


PL Series Torque Requirements

Catalog Number	Number of Holes	GraFoil™		Teflon™	
		ft-lbs	N-m	ft-lbs	N-m
PL-20	2,3,4	90-100	122-136	60-70	81-95
PL-20	6,8	150-165	204-224	90-100	122-136
PL-20	18	250-265	340-360	125-140	170-190
PL-18	1	20-30	27-40	12-15	16-20
PL-18	2,3,4	90-100	122-136	60-70	81-95
PL-18	6,8	150-165	204-224	90-100	122-136
PL-18	10,12	250-265	340-360	125-140	170-190
PL-16	2,3,4	90-100	122-136	60-70	81-95
PL-16	6,8	150-165	204-224	90-100	122-136
PL-16	10,12	250-265	340-360	125-140	170-190
PL-14	1	25-30	34-40	12-15	16-20
PL-14	2	90-100	122-136	60-70	81-95
PL-14	3,4,6,8	150-165	204-224	90-100	122-136
PL-14	10,12	250-265	340-360	125-140	170-190
PL-12	2,3,4,6	150-165	204-224	90-100	122-136
PL-10	2,3,4	150-165	204-224	80-90	108-122
PL-8	2	150-165	204-224	75-85	102-115
PL-8	3	250-265	340-360	125-140	170-190

Minimum recommended wire bend radius – 10 times the wire diameter.

MHM Series

For Hex-Style Models MHM2-MHM5



For assembly separate from the vessel:

1. Verify that the probe length is sufficient for your desired immersion.
2. Thread the cap over the probes with the female thread facing the process (see diagram).
3. Thread the follower over the probes with the keyway towards the cap.
4. Be sure you are using the correct sealant for your working pressure and temperature. Thread the sealant over the probes with the cone facing the process.
5. Thread the seat over the probes with the concave side facing the sealant.
6. Thread the feedthrough body over the probes.
7. Push on the follower until the sealant and seat are firmly positioned in the feedthrough body.
- 8a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 8b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.

9. Thread the cap on finger tight.
10. Secure the feedthrough body into a vice.
11. Make the final adjustment of immersion length.
12. Using a torque wrench, tighten the cap to the specified torque (see chart).
13. The assembly is now ready for use. Apply a wrench to the feedthrough body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:


1. Verify that the probe length is sufficient for your desired immersion.
2. Mount the feedthrough body into the vessel wall.
This may be done by threading or welding, depending on the mounting style. When using a weld mount, the feedthrough must be disassembled prior to welding to protect the sealant.
3. Thread the cap over the probes with the female thread facing the process (see diagram).
4. Thread the follower over the probes with the keyway towards the cap.
5. Be sure you are using the correct sealant for your working pressure and temperature. Thread the sealant over the probes with the cone facing the process.
6. Thread the seat over the probes with the concave side facing the sealant.
7. Insert the probes through the body into the process.
8. Push on the follower until the sealant and seat are firmly positioned in the feedthrough body.
- 9a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 9b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
10. Thread the cap on finger tight.
11. Make the final adjustment of immersion length.
12. Apply a backer wrench to the feedthrough body flats to prevent rotation during torquing.
13. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
14. The assembly is now ready for use.

MHM Series Torque Requirements

Catalog Number	Neoprene		Viton™		Teflon™		Lava		GraFoil™	
	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m
MHM2	25-30	34-40	25-30	34-40	25-30	34-40	25-30	34-40	25-30	34-40
MHM4	80-90	108-122	80-90	108-122	80-90	108-122	125-140	170-190	110-120	150-163
MHM5	120-130	163-176	120-130	163-176	150-165	204-224	200-220	272-299	175-190	238-258

MHM Series

Flange/Cap Models



For assembly separate from the vessel:

1. Verify that the probe length is sufficient for your desired immersion.
2. Thread the flange/cap over the probes (see diagram).
3. Thread the follower over the probes with the counterbore towards the cap.
4. Be sure you are using the correct sealant for your working pressure and temperature. Thread the sealant over the probes with the cone facing the process. (Sealant may be in more than one layer.)
5. Thread the seat over the probes with the concave side facing the sealant.
6. Thread the feedthrough body over the probes.
7. Push on the follower until the sealant and seat are firmly positioned in the feedthrough body.
8. Slide the flange/cap into place after the follower.
9. Thread the 6 cap screws in place and finger tighten.
10. Secure the feedthrough body into a vice.
11. Make the final adjustment of immersion length.
12. Using a torque wrench, tighten the cap screws to 30-35 ft-lbs (40-48 N-m) per bolt. The cap screws should be progressively tightened in the order 1-4-2-5-3-6.
13. The assembly is now ready for use. Apply a wrench to the feedthrough body flats for mounting to the vessel.


For assembly directly into a vessel:

1. Verify that the probe length is sufficient for your desired immersion.
2. Mount the feedthrough body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the feedthrough must be disassembled prior to welding to protect the sealant.
3. Thread the flange/cap over the probes (see diagram).
4. Thread the follower over the probes with the counterbore towards the flange/cap.
5. Be sure you are using the correct sealant for your working pressure and temperature. Thread the sealant over the probes with the cone facing the process. (Sealant may be in more than one layer.)
6. Thread the seat over the probes with the concave side facing the sealant.
7. Insert the assembly through the body.

8. Push on the follower until the sealant and seat are firmly positioned in the feedthrough body.
9. Slide the flange/cap into place to contact the follower.
10. Thread the 6 cap screws in place and finger tighten.
11. Make the final adjustment of immersion length.
12. Use a torque wrench to tighten the cap screws to 30-35 ft-lbs (40-48 N-m) per bolt. The cap screws should be progressively tightened in the order 1-4-2-5-3-6.
13. The assembly is now ready for use.


SPGA and DSPGA Series

(With Load Bearing Washer)



Legacy SPG and DSPG Series

(Without Load Bearing Washer)



For assembly separate from the vessel:

1. Verify that the probe length is sufficient for your desired immersion.
2. Secure the fitting body into a vice.
3. Thread the cap (and load bearing washer if so equipped) over the probes/wires with the female thread facing the process (see diagram).
4. Insert the probes/wires through the body.
5. Assemble the mating halves or quarters of the seat around the probes/wires with the concave side facing away from the process. (Note: Only SPG Series have concave sides.)
6. Slide the assembled seat into the body.
7. Be sure you are using the correct sealant for your working pressure and temperature. Assemble the mating halves or quarters of the sealant around the probes/wires with the cone facing the process. GraFoil™ sealants are numbered sequentially and must be assembled in sequence.
8. Slide the assembled sealant into the body.
9. Assemble the mating halves or quarters of the follower around the probes/wires with the keyway facing the cap.
10. Slide the assembled follower into the body.
11. Push on the follower until the sealant and seat are firmly positioned in the fitting body.
- 12a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.

12b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.

13a. For SPGA or DSPGA with load bearing washer, place washer onto follower with flat side facing cap (see diagram).

13b. For Legacy SPG or DSPG, skip this step.

14. Thread the cap on finger tight. If equipped with load bearing washer, ensure proper seating.

15. Make the final adjustment of immersion length.

16. Using a torque wrench, tighten the cap to the specified torque (see chart).

17. The assembly is now ready for use. Apply a wrench to the fitting body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:

1. Verify that the probe length is sufficient for your desired immersion.
2. Mount the fitting body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.
3. Thread the cap (and load bearing washer if so equipped) over the probes/wires with the female thread facing the process (see diagram).
4. Insert the probes/wires through the body.
5. Assemble the mating halves or quarters of the seat around the probes/wires with the concave side facing away from the process. (Note: Only SPG Series have concave sides.)
6. Slide the assembled seat into the body.
7. Be sure you are using the correct sealant for your working pressure and temperature. Assemble the mating halves or quarters of the sealant around the probes/wires with the cone facing the process.
8. Slide the assembled sealant into the body.
9. Assemble the mating halves or quarters of the follower around the probes/wires with the keyway facing the cap.
10. Slide the assembled follower into the body.
11. Push on the follower until the sealant and seat are firmly positioned in the fitting body.
- 12a. Align the follower keyway and body keyway to create a full keyway, then place pin into the keyway.
- 12b. Align follower with integral pin with body keyway, then insert follower/integral pin into the fitting body/keyway.
- 13a. For SPGA or DSPGA with load bearing washer, place washer onto follower with flat side facing cap (see diagram).
- 13b. For Legacy SPG or DSPG, skip this step.
14. Thread the cap on finger tight. If equipped with load bearing washer, ensure proper seating.
15. Make the final adjustment of immersion length.
16. Apply a backer wrench to the fitting body flats to prevent rotation during torquing.
17. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).

18. The assembly is now ready for use.


SPGA/DSPGA Series Torque Requirements						
with load bearing washer						
Catalog Number	GraFoil™		Lava		Viton™	
	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m
Standard 1/2 NPT						
SPGA100 and DSPGA100	150	204	140	190	90	122
Standard 3/4 NPT						
SPGA150 and DSPGA150	300*	408*	300	408	130	176

* When applying torque to SPGA150 & DSPGA150 models containing GraFoil™ sealants, torque to 275 ft-lbs, then retorque to 300 ft-lbs after 24 hours.

Legacy SPG/DSPG Series Torque Requirements								
without load bearing washer								
Catalog Number	GraFoil™		Lava		Viton™		Teflon™	
	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m
Standard 1/4 NPT								
SPG75 and DSPG75	N/O	N/O	25-30	34-40	25-30	34-40	25-30	34-40
Standard 1/2 NPT								
SPG100 and DSPG100	110-120	150-163	125-140	170-190	80-90	108-122	80-90	108-122
Standard 3/4 NPT								
SPG150 and DSPG150	175-225*	238-306*	200-220	272-299	120-130	163-176	150-165	204-224

N/O = Not Offered.

For Split Fittings – PGS Series



For assembly separate from the vessel:

1. Verify that the probe length is sufficient for your desired immersion.
2. Secure the fitting body into a vice.
3. Thread the cap over the probe with the female thread facing the process (see diagram).
4. Insert the probe through the body.
5. Assemble the mating halves of the seat around the probe with the concave side facing away from the process.
6. Slide the assembled seat into the body.
7. Be sure you are using the correct sealant for your working pressure and temperature. Assemble the mating halves of the sealant around the probe with the cone facing the process.
8. Slide the assembled sealant into the body.


9. Assemble the mating halves of the follower around the probe with the counterbore facing the cap.
10. Slide the assembled follower into the body.
11. Push on the follower until the sealant and seat are firmly positioned in the fitting body.
12. Thread the cap on finger tight.
13. Make the final adjustment of immersion length.
14. Using a torque wrench, tighten the cap to the specified torque (see chart).
15. The assembly is now ready for use. Apply a wrench to the fitting body flats—not the cap—for mounting to the vessel.

For assembly directly into a vessel:

1. Verify that the probe length is sufficient for your desired immersion.
2. Mount the fitting body into the vessel wall. This may be done by threading or welding, depending on the mounting style. When using a weld mount, the fitting must be disassembled prior to welding to protect the sealant.
3. Thread the cap over the probe with the female thread facing the process (see diagram).
4. Insert the probe through the body.
5. Assemble the mating halves of the seat around the probe with the concave side facing away from the process.
6. Slide the assembled seat into the body.
7. Be sure you are using the correct sealant for your working pressure and temperature. Assemble the mating halves of the sealant around the probe with the cone facing the process.
8. Slide the assembled sealant into the body.
9. Assemble the mating halves of the follower around the probe with the counterbore facing the cap.
10. Slide the assembled follower into the body.
11. Push on the follower until the sealant and seat are firmly positioned in the fitting body.
12. Thread the cap on finger tight.
13. Make the final adjustment of immersion length.
14. Apply a backer wrench to the fitting body flats to prevent rotation during torquing.
15. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
16. The assembly is now ready for use.

PGS Series Torque Requirements								
Catalog Number	Viton™		Teflon™		Lava		GraFoil™	
	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m	ft-lbs	N-m
PG2S	30-35	40-48	15-20	20-27	40-45	54-61	35-40	48-54
PG4S	55-60	74-81	55-60	74-81	125-140	170-190	90-100	122-136
PG5S	55-60	74-81	90-100	122-136	200-220	272-299	90-100	122-136

BSWS Series



1. Identify the type of fitting to be assembled. If the sensor leads have an outer jacket or braid, trim this back to the point where it will enter the fitting body when installed (see diagram). This will expose the individual insulated leads.
2. Install the sensor securely in its housing. Place the fitting body over the leads and mount it in the enclosure or bearing housing mounting thread.
3. Slide the sealant with the cone facing the process over the leads into the fitting body until seated. Individual holes are provided for each lead.
4. Slide the follower over the leads and insert it into the fitting body. Ensure that the wires are correctly positioned.
5. Place the cap over the leads and finger tighten.
6. Make the final adjustment of lead length.
7. Apply a backer wrench to the fitting body flats to prevent rotation during torquing.
8. While holding the backer wrench firmly in place, use a torque wrench to tighten the cap to the specified torque (see chart).
9. The assembly is now ready for use.

BSWS Series Torque Requirements

Catalog Number	Viton™	
	ft-lbs	N-m
BSWS4	3-5	4-6
BSWS5	12-15	16-20

Lubricant Application Instructions

Conax Technologies Seal Fittings have lubricant applied at the factory. Substitution of factory-supplied lubricant will affect seal integrity. Lubrication prevents thread galling and minimizes friction between mating metallic components to maximize seal fitting performance when a catalog-specified torque is applied. Lubrication should be used any time a seal fitting assembly is opened for replacement or adjustment of the probe(s), wires or sealant.


By re-lubricating the fitting body threads and load bearing surface of the cap, proper load transfer (sealant compression) can be achieved.

Lubricant kits are available from Conax Technologies in convenient, single application, disposable packages with the applicator included. Conax Technologies recommends use of this lubricant to ensure fitting performance.

CAUTION: Lubricant may cause mild eye irritation. Do not use for lubrication of aluminum or magnesium parts. This product is not an OSHA hazardous material, as defined in 29 CFR1910.120. This product contains CAS# 9002839, Ethene, chlorotrifluoro-homopolymer. 24-Hour Emergency Phone 1-800-733-3665. HMIS Rating System: Health 0, Flammability 0, Reactivity 1. For industrial use only.


Hex-Style Seal Fittings

MK Series



1. Apply a small amount of lubricant, a tear drop equivalent, in two to three places, equally spaced, to the ferrule top. Refer to Figure 1.
2. Apply a single line of lubricant to the full length of the straight thread on the cap. Refer to Figure 1.
3. Assemble the seal fitting per MK Seal Fitting instructions.


PG, MHM, MHC, TG, PL, EG, EGT, SPG, DSPG, PGS and BSWS Series



1. Apply a small amount of lubricant, tear drop equivalent, in two to three places, equally spaced, to the top of the follower. Do not allow the lubricant to directly contact the sealant or the elements you are sealing. Refer to Figure 2.
2. Apply a single line of lubricant to the full length of the straight thread on the fitting body. Refer to Figure 2.
3. Assemble the seal fitting per applicable seal fitting instructions.

Flange/Cap Style Seal Fittings

PG, MHM, EG and EGT Series



1. Apply a small amount of lubricant, tear drop equivalent, in two to three places, equally spaced, to the underside of the hex cap screw on each of the six (6) hex cap screws. Do not allow the lubricant to directly contact the sealant or the elements you are sealing. Refer to Figure 3.
2. Apply a single line of lubricant to the full thread length on each of the six (6) hex head screws. Refer to Figure 3.
3. Assemble the seal fitting. Apply torque per applicable fitting chart.

Chico™ is a trademark of Crouse-Hinds™
CSA™ is a trademark of Canadian Standards Association™
GraFoil™ is a trademark of NeoGraf Solutions™
HASTELLOY™ is a trademark of HAYNES International™
INCONEL™ is a trademark of Special Metals™
Kapton™ is a trademark of E.I. du Pont de Nemours and Company™
Kevlar™ is a trademark of E.I. du Pont de Nemours and Company™

MONEL™ is a trademark of Special Metals™
NEC™ is a trademark of National Fire Protection Association™
PEEK™ is a trademark of Victrex™
Silcolloy™ is a trademark of SilcoTek™
SilcoNert™ is a trademark of SilcoTek™
Silcosteel™ is a trademark of SilcoTek™
Siltek™ is a trademark of SilcoTek™

Sulfinert™ is a trademark of SilcoTek™
Teflon™ is a trademark of The Chemours Company™
Tefzel™ is a trademark of The Chemours Company™
ULTEM™ is a trademark of Shpp Global Technologies™
Vespel™ is a trademark of E.I. du Pont de Nemours and Company™
Viton™ is a trademark of The Chemours Company™